III. <u>REMARK§</u>

Claims 1, 20 and 24 have been amended to more particularly point out that the method includes forming the gap or void to remove a rail defect, but the gap or void does not include the base of the rail and at least a portion of the web remains intact. Antecedency has been corrected in claim 20. Typographical and editing errors have also been corrected in claim 24.

October 5, 2006

Respectfully submitted,

David C. Brezina

Barnes & Thornburg LLP

I C. Borezun

P.O. Box 2786

Chicago, IL 60690

Phone: 312-214-4802 Facsimile: 312-759-5646

Attorney for Applicant Registration No.: 34,128